

City of Detroit
Department of Recreation Performance Audit
Exhibit 2 – Belle Isle Golf Course

Overall Evaluation – Fair Condition

- Broken fence.
- Empty display cases. No items for sale at pro-shop area.
- Parking lot was well maintained.



Broken fence at Belle Isle Driving Range.

City of Detroit
Department of Recreation Performance Audit
Exhibit 2 – Belle Isle Golf Course



This picture shows empty shelves that we were informed were meant to hold pro-shop merchandise.



This parking lot was well maintained with clearly marked parking spaces.

City of Detroit
Department of Recreation Performance Audit
Exhibit 2 – Belle Isle Golf Course



Standing water on the roadway going around the golf course.